

PCN Number:	20160628001	PCN Date:	7/1/2016
Title:	Datasheet for LMV341, LMV342, LMV344		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



LMV341, LMV342, LMV344

SLOS447I – SEPTEMBER 2004 – REVISED MAY 2016

Changes from Revision H (June 2012) to Revision I

Page

• Added ESD Ratings table, Feature Description section, Device Functional Modes, Application and Implementation section, Power Supply Recommendations section, Layout section, Device and Documentation Support section, and Mechanical, Packaging, and Orderable Information section.	1
• Removed Ordering Information table	1

The datasheet number will be changing.

Device Family	Change From:	Change To:
LMV341, LMV342, LMV344	SLOS447H	SLOS447I

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LMV341>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

LMV341IDBVR	LMV342ID	LMV342IDR	LMV344IDRE4
LMV341IDBVRG4	LMV342IDGKR	LMV344ID	LMV344IPW
LMV341IDCKR	LMV342IDGKRG4	LMV342IDRG4	LMV344IDRG4
LMV341IDCKRG4	LMV342IDGKT	LMV344IDG4	LMV344IPWG4
LMV344IPWRE4	LMV344IPWRG4	LMV344IDR	LMV344IPWR

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com