

Product Change Notice

Issue Date: 6/8/2018

Change Type:2nd source for bump**Parts Affected:**

BCM58300 family of parts

Affected MPN:

BCM11300B0KFEBG
BCM11300KFEBG
BCM11320B0KFEBG
BCM11320KFEBG
BCM11350B2KFEBG
BCM11350B3KFEBGT
BCM11350KFEBG

BCM11360KFEBG
BCM58302B3KFEB05G
BCM58302B3KFEB07G
BCM58302MB3KFEB05G
BCM58302QB3KFEB05G
BCM58303B3IFEB10G
BCM58303MB3KFEB10G
BCM58303MB3KFEB12G
BCM58303QB3KFEB10G
BCM58305B0KFEB08G
BCM58305B0KFEB10G
BCM58305B0KFEB12G
BCM58305B3KFEB08G
BCM58305B3KFEB10G
BCM58305B3KFEB12G

Description and Extent of Change:

Adding multiple Bump Suppliers for capacity management.

Only change is on Box label, bump location will be updated to reflect bump house used.

**Reasons for Change:**

Capacity Management

Effect of Change on Fit, Form, Function, Quality, or Reliability:



The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to insure normal parametric distribution, consistent electrical performance, and reliability.

Effective Date of Change:

We are targeting a conversion on WW38

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.