



Product Change Notification - SYST-05UECB861

Date: 08 Dec 2017
Product Category: Ultrasound MOSFET Drivers
Affected CPNs:  
Notification subject: Data Sheet - MD1213 High-Speed Dual-MOSFET Driver Data Sheet Data Sheet Document Revision
Notification text: SYST-05UECB861

Microchip has released a new DeviceDoc for the MD1213 High-Speed Dual-MOSFET Driver Data Sheet of devices. If you are using one of these devices please read the document located at [MD1213 High-Speed Dual-MOSFET Driver Data Sheet](#).

Notification Status: Final

Description of Change: 1) 1. Updated the operating ambient temperature in Absolute Maximum Ratings † and in the Temperature Specifications table 2) Made minor text changes throughout the document

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 08 Dec 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [MD1213 High-Speed Dual-MOSFET Driver Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

MD1213K6-G