

<b>PCN Number:</b>	20170607000	<b>PCN Date:</b>	July 31, 2017
<b>Title:</b>	Datasheet for TPS65197		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Proposed 1<sup>st</sup> Ship Date:</b>	October 31, 2017		
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below.



**TPS65197, TPS65197B**

SLVSBB0C – APRIL 2012 – REVISED MAY 2017

**Changes from Revision B (July 2015) to Revision C**

**Page**

- Changed  $V_{IH}$  MIN value from 2 to 1.65 in the INPUT SIGNALS section of the Electrical Characteristics table..... **5**

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS65197	SLVSBB0B	SLVSBB0C

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TPS65197>

#### Reason for Change:

To more accurately reflect device characteristics.

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

#### Changes to product identification resulting from this PCN:

None.

#### Product Affected:

TPS65197BRUYR	TPS65197BRUYT	TPS65197RUYP	
---------------	---------------	--------------	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>