

## Product Change Notification

(Notification - P1707037-DIGI)

(HMRL-AC-17-0002)

July 13, 2017

**To:** *Our Valued Digi-Key Electronics Customer*

**Overview:** The purpose of this notification is to communicate a product change of select Renesas Electronics America, Inc. (REA) devices. These devices have suggested replacements.

A circuit change in the R8C/L3xC and R8c/L3xM microcomputer products eliminates the restrictions on the wait mode. This change results in a part number change. There are no changes to product reliability and electrical specifications.

For further details on the restriction, see the Renesas Technical Update Document: TN-R8C-A057B/E.

**Affected Products:** A review of our records indicate the list of products in the appendix may affect your company.

Part numbers given in this list are for active part numbers in REA database at the time of this notification.

**Key Dates:**

Replacement devices available.
--------------------------------

<b>Aug. 15<sup>th</sup>, 2017</b>
-----------------------------------

**Response:** No response is required. REA will consider this notification approved 30 days after its issue. Please switch to replacement device as soon as possible to avoid disruption of supply. You are encouraged to sample the suggested replacement device and begin qualification as soon as possible. Please contact you REA sales representative to obtain samples.

If the customer provides a timely acknowledgement, the customer shall have 90 days (an additional 60 days) from the date of receipt of this notification in which to make any objections to the notification. If the customer does not make any objections to this notification within 90 days of the receipt of the notification, then Renesas will consider the notification as approved. If customer cannot accept the notification, then the customer must provide Renesas with a last time buy demand and purchase order.

Please contact your REA sales representative for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics America, Inc.

Appendix: P1707037-DIGI Affected Part Numbers

Booking Part Number	Suggested Replacement Part Number	Booking Part Number	Suggested Replacement Part Number
R5F2L357CNFP#30	R5F2L357CNFP#31	R5F2L38CCNFP#30	R5F2L38CCNFP#31
R5F2L357CNFP#50	R5F2L357CNFP#51	R5F2L38CMDFA#V0	R5F2L38CMDFA#V1
R5F2L35CCDFP#30	R5F2L35CCDFP#31	R5F2L38CMNFA#V0	R5F2L38CMNFA#V1
R5F2L35CCNFP#30	R5F2L35CCNFP#31	R5F2L3A7CDFA#U0	R5F2L3A7CDFA#U1
R5F2L368CDFA#30	R5F2L368CDFA#31	R5F2L3A7CNFA#U0	R5F2L3A7CNFA#U1
R5F2L368CDFP#30	R5F2L368CDFP#31	R5F2L3A7CNFP#30	R5F2L3A7CNFP#31
R5F2L368CNFP#30	R5F2L368CNFP#31	R5F2L3A7MDFA#U0	R5F2L3A7MDFA#U1
R5F2L36CCNFA#30	R5F2L36CCNFA#31	R5F2L3A7MNFA#U0	R5F2L3A7MNFA#U1
R5F2L387CDFA#V0	R5F2L387CDFA#V1	R5F2L3A8CDFA#U0	R5F2L3A8CDFA#U1
R5F2L387CNFA#V0	R5F2L387CNFA#V1	R5F2L3A8CNFA#U0	R5F2L3A8CNFA#U1
R5F2L387CNFP#30	R5F2L387CNFP#31	R5F2L3A8MDFA#U0	R5F2L3A8MDFA#U1
R5F2L387MDFA#V0	R5F2L387MDFA#V1	R5F2L3A8MNFA#U0	R5F2L3A8MNFA#U1
R5F2L387MNFA#V0	R5F2L387MNFA#V1	R5F2L3AACDFFA#U0	R5F2L3AACDFFA#U1
R5F2L388CDFA#V0	R5F2L388CDFA#V1	R5F2L3AACNFA#U0	R5F2L3AACNFA#U1
R5F2L388CNFA#V0	R5F2L388CNFA#V1	R5F2L3AACNFP#30	R5F2L3AACNFP#31
R5F2L388MDFA#V0	R5F2L388MDFA#V1	R5F2L3AAMDFA#U0	R5F2L3AAMDFA#U1
R5F2L388MNFA#V0	R5F2L388MNFA#V1	R5F2L3AAMNFA#U0	R5F2L3AAMNFA#U1
R5F2L38ACDFFA#V0	R5F2L38ACDFFA#V1	R5F2L3ACCDFA#U0	R5F2L3ACCDFA#U1
R5F2L38ACNFA#V0	R5F2L38ACNFA#V1	R5F2L3ACCNFA#U0	R5F2L3ACCNFA#U1
R5F2L38AMDFA#V0	R5F2L38AMDFA#V1	R5F2L3ACCNFP#30	R5F2L3ACCNFP#31
R5F2L38AMNFA#V0	R5F2L38AMNFA#V1	R5F2L3ACMDFA#U0	R5F2L3ACMDFA#U1
R5F2L38CCDFFA#V0	R5F2L38CCDFFA#V1	R5F2L3ACMNFA#U0	R5F2L3ACMNFA#U1
R5F2L38CCNFA#V0	R5F2L38CCNFA#V1	R5F2L3ACMNFP#30	R5F2L3ACMNFP#31