

PCN Number:	20160606002	PCN Date:	06/17/2016
Title:	Datasheet for OPA376-Q1/OPA2376-Q1/OPA4376-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is updated as seen in the change revision history below:



OPA376-Q1, OPA2376-Q1, OPA4376-Q1

SBOS549B – APRIL 2011 – REVISED JUNE 2016

www.ti.com

Changes from Revision A (January 2016) to Revision B

Page

• Updated <i>Applications</i> examples	1
• Updated the <i>Pin Functions Table</i> for OPA4376-Q1	5
• Updated <i>HBM ESD Rating</i>	6
• Changed units on <i>Channel Separation</i>	8
• Deleted the temperature range parameters from the <i>Electrical Characteristics</i> table.....	9
• Removed section regarding <i>WCSP photosensitivity</i>	23

Device Family	Change From:	Change To:
OPA376-Q1/OPA2376-Q1/OPA4376-Q1	SBOS549A	SBOS549B

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/opa376-q1>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

OPA2376AQDRQ1	OPA2376QDGKRQ1	OPA376AQDBVRQ1
---------------	----------------	----------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com