

April 13, 2011

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC11027 – Product EOL/Obsolescence Notification**

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB/WTHD date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP/OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

*Carl Sapp
GCCN Customer Relations Dept.
Intersil Corporation*

Exact Intersil Part # No other variation is being impacted.	Notice PLC11027 Date	LTB / WTHD DATE	SHIP/ OBSOLETE DATE	Replacement/ Similar/ Re-Design
5962-87677012A	13-Apr-11	28-Oct-11	13-Apr-12	NONE
5962-9306301M2A	13-Apr-11	28-Oct-11	13-Apr-12	NONE
BBT3420-SN	13-Apr-11	28-Oct-11	13-Apr-12	NONE
EL1516AIYZ	13-Apr-11	28-Oct-11	13-Apr-12	EL5236IYZ
EL1516ISZ	13-Apr-11	28-Oct-11	13-Apr-12	EL5236ISZ
EL1516IYZ	13-Apr-11	28-Oct-11	13-Apr-12	EL5236IYZ
EL1537BIREZR5396	13-Apr-11	28-Oct-11	13-Apr-12	NONE
EL1537BIREZ-T13R5396	13-Apr-11	28-Oct-11	13-Apr-12	NONE
EL1537BIREZ-T7R5396	13-Apr-11	28-Oct-11	13-Apr-12	NONE
HA0-5320B5454-6	13-Apr-11	28-Oct-11	13-Apr-12	NONE
HA0-5330B5454-6	13-Apr-11	28-Oct-11	13-Apr-12	NONE
HA1-5320-2	13-Apr-11	28-Oct-11	13-Apr-12	NONE
HCTS86DMSR	13-Apr-11	28-Oct-11	13-Apr-12	NONE
5962R9581401VCC	13-Apr-11	28-Oct-11	13-Apr-12	NONE
HCTS86HMSR	13-Apr-11	28-Oct-11	13-Apr-12	NONE
5962R9581401V9A	13-Apr-11	28-Oct-11	13-Apr-12	NONE
HCTS86KMSR	13-Apr-11	28-Oct-11	13-Apr-12	NONE
5962R9581401VXC	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL1540IRZ-T13	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL1540IRZ-T7	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL22319UFU8Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22316UFU10Z
ISL22319UFU8Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22316UFU10Z-TK
ISL22319WFU8Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22316WFU10Z
ISL22319WFU8Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22316WFU10Z-TK
ISL22329UFU10Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22326UFV14Z
ISL22329UFU10Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22326UFV14Z-TK
ISL22329WFU10Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22326WFV14Z
ISL22329WFU10Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22326WFV14Z-TK
ISL22349UFV14Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22346UFV20Z
ISL22349UFV14Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22346UFV20Z-TK
ISL22349WFV14Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22346WFV20Z
ISL22349WFV14Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22346WFV20Z-TK
ISL22419UFU8Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22416UFU10Z
ISL22419UFU8Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22416UFU10Z-TK
ISL22419WFU8Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22416WFU10Z
ISL22419WFU8Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22416WFU10Z-TK
ISL22429UFU10Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22426UFV14Z
ISL22429UFU10Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22426UFV14Z-TK
ISL22429WFU10Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22426WFV14Z
ISL22429WFU10Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22426WFV14Z-TK
ISL22449UFV14Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22446UFV20Z
ISL22449UFV14Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22446UFV20Z-TK
ISL22449WFV14Z	13-Apr-11	28-Oct-11	13-Apr-12	ISL22446WFV20Z
ISL22449WFV14Z-TK	13-Apr-11	28-Oct-11	13-Apr-12	ISL22446WFV20Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC11027 Date	LTB / WTHD DATE	SHIP/ OBSOLETE DATE	Replacement/ Similar/ Re-Design
ISL29000IROZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29000IROZ-EVALZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29000IROZ-T7	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29001IROZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29002IROZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29002IROZ-EVALZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29002IROZ-T7	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29003IROZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29004IROZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29004IROZ-T7	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL2900IROZ-EVALZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29012IROZ-EVALZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL29012IROZ-T7	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL34340INZ	13-Apr-11	28-Oct-11	13-Apr-12	NONE
ISL34340INZ-T13	13-Apr-11	28-Oct-11	13-Apr-12	NONE
X28HC256JIZ12T1S2705	13-Apr-11	27-Jan-12	30-Jan-13	NONE
X28HC64JIZ-12T1S2705	13-Apr-11	27-Jan-12	30-Jan-13	NONE
X28HC64JZ-12T1S2705	13-Apr-11	27-Jan-12	30-Jan-13	NONE
X9313WMIZ-3C7886	13-Apr-11	28-Oct-11	13-Apr-12	X9313WMIZ-3
X9313WMIZ-3T1C7886	13-Apr-11	28-Oct-11	13-Apr-12	X9313WMIZ-3T1
X9314WMIZ-3C7886	13-Apr-11	28-Oct-11	13-Apr-12	X9314WMIZ-3
X9314WMIZ-3T1C7886	13-Apr-11	28-Oct-11	13-Apr-12	X9314WMIZ-3T1
ZL1505ALNNT	13-Apr-11	13-Apr-11	13-Apr-11	ZL1505ALNFT
ZL1505ALNNT1	13-Apr-11	13-Apr-11	13-Apr-11	ZL1505ALNFT1
ZL1505ALNNT6	13-Apr-11	13-Apr-11	13-Apr-11	ZL1505ALNFT6
ZL2004ALNN	13-Apr-11	13-Apr-11	13-Apr-11	ZL2004ALNF
ZL2004ALNN-01	13-Apr-11	13-Apr-11	13-Apr-11	ZL2004ALNF-01
ZL2004ALNNT	13-Apr-11	13-Apr-11	13-Apr-11	ZL2004ALNFT
ZL2004ALNNT-01	13-Apr-11	13-Apr-11	13-Apr-11	ZL2004ALNFT-01
ZL2004ALNNT1	13-Apr-11	13-Apr-11	13-Apr-11	ZL2004ALNFT1
ZL2004ALNNT1-01	13-Apr-11	13-Apr-11	13-Apr-11	ZL2004ALNFT1-01
ZL2008ALAFT	13-Apr-11	13-Apr-11	13-Apr-11	ZL2008ALBFT
ZL2008ALAFT1	13-Apr-11	13-Apr-11	13-Apr-11	ZL2008ALBFT1
ZL2014ALANT-01	13-Apr-11	13-Apr-11	13-Apr-11	ZL2014ALAFT-01
ZL2014ALANT1-01	13-Apr-11	13-Apr-11	13-Apr-11	ZL2014ALAFT1-01
ZL2014ALANT6-01	13-Apr-11	13-Apr-11	13-Apr-11	ZL2014ALAFT6-01
ZL2014ALANT6-01R5448	13-Apr-11	13-Apr-11	13-Apr-11	None
ZL2103ALAN	13-Apr-11	13-Apr-11	13-Apr-11	ZL2103ALAF
ZL2103ALANT	13-Apr-11	13-Apr-11	13-Apr-11	ZL2103ALAFT
ZL2103ALANTK	13-Apr-11	13-Apr-11	13-Apr-11	ZL2103ALAFTK
ZL2106ALBN	13-Apr-11	13-Apr-11	13-Apr-11	ZL2106ALCF
ZL2106ALBNT	13-Apr-11	13-Apr-11	13-Apr-11	ZL2106ALCFT
ZL2106ALBNTK	13-Apr-11	13-Apr-11	13-Apr-11	ZL2106ALCFTK
ZL2106ALCN	13-Apr-11	13-Apr-11	13-Apr-11	ZL2106ALCF

Exact Intersil Part # No other variation is being impacted.	Notice PLC11027 Date	LTB / WTHD DATE	SHIP/ OBSOLETE DATE	Replacement/ Similar/ Re-Design
ZL2106ALCNT	13-Apr-11	13-Apr-11	13-Apr-11	ZL2106ALCFT
ZL2106ALCNTK	13-Apr-11	13-Apr-11	13-Apr-11	ZL2106ALCFTK
ZL2106ALCNTR5451	13-Apr-11	13-Apr-11	13-Apr-11	None
ZL8100ALAN	13-Apr-11	13-Apr-11	13-Apr-11	ZL8100ALAF
ZL8100ALANT	13-Apr-11	13-Apr-11	13-Apr-11	ZL8100ALAFT
ZL8100ALANTK	13-Apr-11	13-Apr-11	13-Apr-11	ZL8100ALAFTK
ZL8100ALANTKR5457	13-Apr-11	13-Apr-11	13-Apr-11	ZL8100ALAFTKR5457
ZL8101ALAN	13-Apr-11	13-Apr-11	13-Apr-11	ZL8101ALAF
ZL8101ALANT	13-Apr-11	13-Apr-11	13-Apr-11	ZL8101ALAFT
ZL8101ALANTK	13-Apr-11	13-Apr-11	13-Apr-11	ZL8101ALAFTK