




 Search ...

PRODUCTS | APPLICATIONS | DESIGN SUPPORT | TRAINING | SAMPLE AND BUY | ABOUT
US | CONTACT US | myMicrochip Login

Product Change Notification - SYST-20AFGN730

Date:	21 Jun 2016
Product Category:	8-bit Microcontrollers
Affected CPNs:	 
Notification subject:	ERRATA - PIC32MM0064GPL036 Family Silicon Errata and Data Sheet Clarification Errata Document Revision
Notification text:	SYST-20AFGN730

Microchip has released a new DeviceDoc for the PIC32MM0064GPL036 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC32MM0064GPL036 Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Corrected the codes in silicon issue 2 (ADC). 2) Added silicon issue 5 (Primary XT and HS Oscillator (POSC)).

Pre Change: 1) "1023, 2047, 2048 and 3071"

Post Change: 1) "1023, 2046, 2047 and 3071" 2) "Module: Primary (Crystal) Oscillator (POSC) Issue: The Primary Oscillator Start-up Timer (OST) may indicate the oscillator is stable enough for use and set the CLKSTAT bit too early..."

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 21 Jun 2016

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [PIC32MM0064GPL036 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



Products | Applications | Design Support | Training | Sample and Buy | About Us |
Contact Us | Legal | Investors | Careers | Support

©Copyright 1998-2016 Microchip Technology Inc. All rights reserved. Shanghai ICP
Recordal No.09049794

Affected Catalog Part Numbers (CPN)

PIC32MM0016GPL020T-I/SS
PIC32MM0016GPL020T-I/ML
PIC32MM0016GPL020-I/SS
PIC32MM0016GPL020-I/ML
PIC32MM0032GPL020T-I/SS
PIC32MM0032GPL020T-I/ML
PIC32MM0032GPL020-I/SS
PIC32MM0032GPL020-I/ML
PIC32MM0064GPL020T-I/SS
PIC32MM0064GPL020T-I/ML
PIC32MM0064GPL020-I/SS
PIC32MM0064GPL020-I/ML
PIC32MM0016GPL028T-I/MV
PIC32MM0016GPL028-I/SP
PIC32MM0016GPL028-I/MV
PIC32MM0016GPL028T-I/SS
PIC32MM0016GPL028T-I/SO
PIC32MM0016GPL028T-I/ML
PIC32MM0016GPL028T-I/M6
PIC32MM0016GPL028-I/SS
PIC32MM0016GPL028-I/SO
PIC32MM0016GPL028-I/ML
PIC32MM0016GPL028-I/M6
PIC32MM0032GPL028T-I/MV
PIC32MM0032GPL028-I/SP
PIC32MM0032GPL028-I/MV
PIC32MM0032GPL028T-I/SS
PIC32MM0032GPL028T-I/SO
PIC32MM0032GPL028T-I/ML
PIC32MM0032GPL028T-I/M6
PIC32MM0032GPL028-I/SS
PIC32MM0032GPL028-I/SO
PIC32MM0032GPL028-I/ML
PIC32MM0032GPL028-I/M6
PIC32MM0064GPL028T-I/MV
PIC32MM0064GPL028-I/MV
PIC32MM0064GPL028T-I/SS
PIC32MM0064GPL028T-I/SO
PIC32MM0064GPL028T-I/ML
PIC32MM0064GPL028-I/SS
PIC32MM0064GPL028-I/SP
PIC32MM0064GPL028-I/SO
PIC32MM0064GPL028-I/ML
PIC32MM0016GPL036T-I/MV
PIC32MM0016GPL036T-I/M2
PIC32MM0016GPL036-I/MV
PIC32MM0016GPL036-I/M2

PIC32MM0032GPL036T-I/M2
PIC32MM0032GPL036-I/MV
PIC32MM0032GPL036-I/M2
PIC32MM0064GPL036T-I/MV
PIC32MM0064GPL036T-I/M2
PIC32MM0064GPL036-I/MV
PIC32MM0064GPL036-I/M2