



Product Discontinuance Notice - PDN 22_0081 Rev. A

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of Select ADM1293-2 Products

Publication Date: 09-Mar-2023

Last Time Buy Date: 06-Mar-2023

Last Time Ship Date: 07-Mar-2023

Revision Description:

Change LTB to immediate due to no manufacturing capabilities

Reason For Discontinuance

Part can no longer be manufactured.

Comments

Recommended replacement part is pin to pin compatible ADM1293-1, customer will need to change the firmware.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 22_0081 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADM1293-2AAPZ	ADM1293	ADM1293-1AAPZ	YES	Require a FW change
ADM1293-2AAPZ-RL	ADM1293	ADM1293-1AAPZ-RL7	YES	Require a FW change

Appendix A - PDN 22_0081 Revision History

Rev	Publish Date	Rev Description
Rev. -	23-Sep-2022	Initial Release
Rev. A	09-Mar-2023	Change LTB to immediate due to no manufacturing capabilities

Analog Devices, Inc. Proprietary Information

DocId:1943 Layout Rev:3 Parent DocId:None