



Not Recommended for New Designs: HY Series Signal Relays

NRFND.PG01.01.04.2023

01.04.2023

About This Notice:	The HY Series Signal Relays are not recommended for new designs due to possible plans for discontinuation in the future.
Features:	
Effective Date:	01.04.2023
Affected Parts and/or Replacements:	See Attached
Datasheet(s):	See Attached
Notes:	

Panasonic NRFND.PG01.01.04.2023 HY Series Signal Relays Affected Parts

Affected Part Numbers

HY1-1.5V
HY1-12V
HY1-24V
HY1-3V
HY1-4.5V
HY1-5V
HY1-6V
HY1-9V
HY1Z-1.5V
HY1Z-12V
HY1Z-24V
HY1Z-3V
HY1Z-4.5V
HY1Z-5V
HY1Z-6V
HY1Z-9V